

State J. Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Supervisor <u>U</u>

Report Date: April 4, 2007

Mine Name: Rhyolite 1 Operator Name: Color Country Rock Preston Hafen 115 South Main Veyo, Utah 84782 Inspector(s): Doug Jensen, Daron Haddock Other Participants: None	Permit number: S/021/032 Date: February 12, 2007 Time: 4:30 PM		
Mine Status: Inactive	Weather: Clear, mild		
Elements of Inspection 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality 12. Other Purpose of Inspection:	Evaluated	Comment	Enforcement
Inspected the site while in the area. Directions to Site: This site is located approximately three miles west of Beryl Junction near Highway 56. Inspection Summary: There have been no changes to this site since it was last inspected. The piles of materials remain the same as they were several years ago. The site is stable with no environmental concerns. Conclusions and Recommendations: Continue to monitor the site when in the area. Inspector's Signature Addlack Date: 446.7			
cc: Color Country Rock P:\GROUPS\MINERALS\WP\M021-Iron\S0210032-RhyoliteQuarry\	inspections\0212	22007insp.doc	